



Photo 4. End view of the East end rail segment at the POD and the internal rail defect that measured 24 1/2 inches from the East end bolted rail joint