



Photo 6. End View of the second internal defect that measured 98 1/2 inches from the East end bolted rail