

ITEM NO. 17

BNSF Track Inspection Reports from January 2, 2001 thru March 17, 2001

DIVISION <i>Web</i>		SUBDIVISION <i>Croston</i>		DATE <i>1/5/01</i>	
INSPECTION BY: SIGNATURE <i>[Signature]</i>				DAY <i>Friday</i>	
INSPECTED MP - MP	FRA CLASS	NO. T.O.'S & X-INGS INSPECTED	NO. OF SIDINGS INSPECTED	NO. YARD & BACKTKS INSPECTED	LOCATION - DESCRIPTION
<i>429.2 391</i>	<i>4</i>	<i>2</i>			<i>Power covers MP 425.5 Trk CNE</i>
		<i>1</i>			<i>MP 422.9 Elev Trk Nodaway</i>
		<i>1</i>			<i>Power SW MP 422.2</i>
		<i>1</i>			<i>Industry SW MP 415.8</i>

TRACK DEFECTS (FRA)

LOCATION	DESCRIPTION	CORRECTIVE ACTION AND DATE
<i>MP 425.5</i>	<i>133.09 (2)</i>	<i>Tightened 1/5/01</i>
<i>MP 425.5</i>	<i>133.12</i>	<i>Replaced 1/5/01</i>
<i>MP 422.9</i>	<i>133.06</i>	<i>Tightened 1/5/01</i>
<i>MP 422.2</i>	<i>133.09 (5)</i>	<i>Tightened 1/5/01</i>
<i>MP 415.8</i>	<i>121.03</i>	<i>Replaced 1/5/01</i>
<i>MP 415.8</i>	<i>133.09</i>	<i>Tightened 1/5/01</i>
<i>MP 414.6</i>	<i>121.03</i>	<i>Replaced 1/5/01</i>

LOCATION	DESCRIPTION	CORRECTIVE ACTION AND DATE
422.9	121.05	Replace bolt 1-8-01

TRACK DEFECTS (FRA)

DIVISION	SUBDIVISION	DATE	INSPECTION BY SIGNATURE	DAY	LOCATION - DESCRIPTION	INSPECTED MP - MP	FRA CLASS	NO. T.O.S. INSPECTED	NO. OF SIDINGS INSPECTED	NO. YARD & BACKS INSPECTED
		1-8-01	<i>John R. Miller</i>	Monday		427.00	4			
						427.20	4			
						427.05	1			
						425.5	4			
						422.9	2			
						422.2	2			
						406.8	2			
						406.4	2			
						405.7	1			
						395.2	1			

