

BNSF Report of recorded Rail Defects Between MP 419.5 and MP 420.0

ITEM NO. 10

**All Rail Defects On LS 1  
Between MP 419.5 and MP 420.5  
on Track (S)  
Between 01/01/2001 and 03/19/2001**

Line Seg	Mile Post	Track	Test Date	Det Car	Rail Wgt	Rail Sec	Rail Pos	Year Rolled	Seq Nbr	Rail Mfg	Def Type
1	419.920	S	02/13/2001	HR2013	132	RE	5 1 7/16"	1974	61	IL	D-13
Defect Total											1

**All Rail Defects On LS 1  
Between MP 419.5 and MP 420.6  
on Track (S)  
Between 01/01/2000 and 12/31/2000**

Line Seg	Mile Post	Track	Test Date	Det Car	Rail Wgt	Rail Sec	Rail Pos	Year Rolled	Seq Nbr	Rail Mfg	Def Type
1	419.600	S	11/03/2000	SERVIC	132	RE N	6 HL	1978	0	BE	DF 13
		S	12/19/2000	HR2013	132	RE S	1 TAN	1977	270	IL	T/W 61
	419.620	S	11/20/2000	HR2013	136	RE N	4 TAN	1947	228	IL	SNB 32
Defect Total											3

**All Rail Defects On LS 1  
Between MP 419.5 and MP 420.6  
on Track (S)  
Between 01/01/1999 and 12/31/1999**

Line Seg	Mile Post	Track	Test Date	Det Car	Rail Wgt	Rail Sec	Rail Pos	Year Rolled	Seq Nbr	Rail Mfg	Def Type
1	419.770	S	09/13/1999	SRS812	132	RE	N 4 TAN	1979	285	IL	DF 13
	419.800	S	09/13/1999	SRS812	132	RE	N 4 TAN	1972	283	IL	CH 23
	419.910	S	10/18/1999	SRS812	132	RE	S 1 TAN	1979	405	IL	CH 23
	419.920	S	09/13/1999	SRS812	132	RE	S 1 TAN	1974	284	IL	CH 23
		S	10/18/1999	SRS812	132	RE	S 1 TAN	1988	406	ST	DF 13
Defect Total											5

**All Rail Defects On LS 1  
Between MP 419.5 and MP 420.0  
on Track (S)  
Between 01/01/1998 and 12/31/1998**

Line Seg	Mile Post	Track	Test Date	Det Car	Rail Wgt	Rail Sec	Rail Pos	Year Rolled	Seq Nbr	Rail Mig	Def Type
1	419.850	S	09/30/1998	SRS809	132	OT	S 1 TAN	1974	353	IL	DF 13
	419.860	S	09/30/1998	SRS809	132	OT	N 4 TAN	1975	352	OT	KH 23
	419.900	S	01/27/1998	SPER09	132	RE	S 1 TAN	1975	56	TN	CH 23
	419.970	S	09/30/1998	SRS809	132	OT	N 4 TAN	1974	351	CF	TF 18
Defect Total											4