

ITEM NO. 12

**Track Geometry Vehicle Inspection Report**

# DETAIL of Geometry Defects with "Red Tag Repair" Information

DEFECT STATUS: ALL DEFECTS

DEFECT PRIORITY: —All—

REGION:

DIVISION:

SUBDIVISION:

ROADMASTER: —All—

FROM: 08/01/2000

TO: 3/19/2001

LINE SEGMENT: 0001

BEG MP: 415

END MP: 425

TRACK TYPE: —All—

TRACK NBR: —All—

REGION	DIVISION	C/C	ROADMASTER	TEST DATE	CAR	LS	TRK TYPE	TRK NBR	DEF NBR	MILE POST	DEF LEN	PRIORITY	DEFEC TYPE	DEF SIZE	CORRECTED DATE
--------	----------	-----	------------	-----------	-----	----	----------	---------	---------	-----------	---------	----------	------------	----------	----------------

DENVER

NEBRASKA

13631

JANSEN	2000-08-28	80	1	M	0	100482142	418.889	4	YEL	WARP62:62	-1.78
JANSEN	2000-08-28	80	1	M	0	100482141	418.901	7	YEL	DIP	-1.54
JANSEN	2000-08-10	80	1	M	0	100446053	418.946	5	YEL	DIP	-0.93
JANSEN	2000-08-28	80	1	M	0	100482140	420.556	9	YEL	XLEVEL	-1.27
JANSEN	2000-08-28	80	1	M	0	100482139	420.561	4	YEL	XLEVEL	-1.23
JANSEN	2000-08-10	80	1	M	1	100446054	423.565	1	YEL	XLEVEL	1.18
JANSEN	2000-08-10	80	1	M	1	100446055	423.569	3	YEL	XLEVEL	1.20

Cost Center Subtotals	GRMS	TANK	GAGE	WARP	SURFACE	LNBAL	ALIGN			
	0	0	0	0	0	0	0	33	7	0
YEL	7	0	0	0	1	6	0			
Division Subtotals								33	7	0
	0	0	0	0	0	0	0			
YEL	7	0	0	0	1	6	0			
Region Subtotals								33	7	0
	0	0	0	0	0	0	0			
YEL	7	0	0	0	1	6	0			
Grand Totals								33	7	0
	0	0	0	0	0	0	0			
YEL	7	0	0	0	1	6	0			